

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17490 Main Street: WINDEMERE_LN **Cross Street: WORDSWORTH_LN** Location: S **Overall Compliance: No ADA ID: 16C7E1B1A12C** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 1.25

Codes/Mitigation Info/Possible Solution



WINDEMERE LN Street 1 Name StopSign Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	Co		
Remove & Replace Entire Ramp.			
•	Ye		
	N/		
Surveyor Notes:	N/		
N/A	N/		
	N/		
	N/		
	N/		
PROW/ADA:	N/		
Not Found, R304.5.3			
	N/		
	N/		

Total Cost: 1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	46.0	Yes	Ram	Slope (%)	5.6		
Yes	Ramp Width (in)	48.0	No	Ram	XSlope (%)	2.4		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.2		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	7.8		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		





