

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6628	Main Street: EARLY_MIST_LN				Cross Street: COCHRANE_DR				Location:	NE
ADA ID: 176BCB9D9356	Ramp Ty	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complian			lo Severity Score:	10
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	· · · · · · · · · · · · · · · · · · ·	Possible Solutions:			Compliance Description			Data Compliance Description		
		Remove & R	eplace Entire	Ramp.	N/A	Ramp Length LT (in)	27.5	N/A	Ramp Length RT (in)	47.0
					No	Ramp Width LT (in)	47.0	No	Ramp Width RT (in)	47.0
5					Yes	Ramp Slope LT (%)	3.8	Yes	Ramp Slope RT (%)	6.3
	Z inthe				No	Ramp XSlope LT (%)	3.1	No	Ramp XSlope RT (%)	4.3
	State State				N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	8.0
					No	Ramp Width (in)	37.5	No	Ramp XSlope (%)	2.9
	ANA L	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the second se	· 1.80	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
COCHRANE DE					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	5 <u>6</u>				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	· · · · · · · · · · · · · · · · · · ·	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the start	120	Not Found.	R304.5.1, R304	4.5.1.	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second second		R304.5.3	,,	,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	anna (March 48)				N/A	Shared Landing?	N/A			
	AL AN				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	EARLY MIST LN				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	5.3		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	\$ 1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
								N/A	Any Obstruction?	N/A
		untering senting			T				Obstruction Type	
				-						N/A
			-					N/A	Storm Grate/Utility Hazard?	N/A

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 9.2





