cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25521	Main Street: PINEVILLE-MATTHEWS_RD			Cross Street: MCPHERSON_DR				Location:	NW
ADA ID: 17BCD1039332	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	CE MAN	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	132.0	N/A	Grade Break?	N/A
	1			Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	0.0
	日日的一级一个			No	Ramp Slope (%)	9.5	N/A	Grade Break XSlope (%)	0.0
	19 20 Car 18			No	Ramp XSlope (%)	2.3			
	The let			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	L Tomas			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	A ANDA	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
6 6 M	WS RD			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
PINEVILLE-MAILUR				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	- della -	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
See The second second second second	A STATE OF A	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
The second second	The second second	,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
A CARLEN AND A CARLEN AND A	A STATE			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	1.2
Street 1 Name	MCPHERSON DR				X Walk 1 Direction	To NE		Road X Slope (%)	2.8
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	6.9

