

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.4

1.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 45550 Main Street: PEACHTREE RD Cross Street: ROOK RD Location: Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 17FF251D91E0 Ramp Type: Perp Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Data

48.0

46.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Flare Slope LT (%) Flare Traversable LT?



ROOK RD Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solution		rieia ivie
Possible Solutions:	Compl	iance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	No	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
R304.5.1, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk
		D 101 (0/)



Total Cost:





Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To S X Walk 2 Direction N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 1.3 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 0.7 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** 1850.00 Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good