cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040760 Main Street: W_TYVOLA_RD C				N/A	Location:	NE			
	Ramp Type: PerpDiag		Cross Street: N/A Initial Pass/Fail: Fail Overall Compliance: No						
· · · · · ·		millari	455/1 0			13.75			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data	
	Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.	lith	N/A	Ramp Length (in)	100.0	No	Ramp Slope (%)	8.6	
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.0	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	12		N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To W		X Walk 2 Direction	To S	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name W TYVOLA RD				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	5.8	
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	4.1		X Walk 2 X Slope (%)	0.9	
Street 2 Name ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSign				Road Slope (%)	3.3		Clear Space?	N/A	
				Road X Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
	····· • • •				N/A			N/A	

Yes Surface Condition? (G/P)

Good

