

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Obstruction Type

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Yes

N/A

N/A

N/A

Good

21.5

Intersection ID: 9129	Main Str	Main Street: N_GRAHAM_ST				NORRIS_AV	Location:	sw		
ADA ID: 1834A6D26669	Ramp Ty	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Compliance: No				58.75
Codes		Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 58.75 Field Measurements/Component Compliance								
	18 1 1	Possible Solutions:						Compliance Description Data		
A Aller .	En / /	Remove & Replace Ent	Entire Ramp		N/A	Ramp Length LT (in)	57.0	N/A	Ramp Length RT (in)	65.0
	RY III		ne na	mp.	Yes	Ramp Width LT (in)	60.0		Ramp Width RT (in)	60.0
					Yes	Ramp Slope LT (%)	5.7	No	Ramp Slope RT (%)	14.0
A No IE					Yes	Ramp XSlope LT (%)	2.0	No	Ramp XSlope RT (%)	2.1
	$\times 1 \wedge \mathbb{A}$				N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.6
A CONTRACTOR	BAN WAS				No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	10.1
A P S A P S	H E	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6 S	y s				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1. 1. 1. 1. 1.	1 AN				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	t a .				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	CL CLS	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Not Found, R304.5.1, R304.5.3,			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A 11/1/19	And I	R304.3.2			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
all the	The set				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	NORRIS AV				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	116.0		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	10.0		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			1	and the second s	//	dit -		N/A	Any Obstruction?	N/A

