

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | |
|---------------------------|----------------------------|----------------------------|------------------------|-------------------|
| Intersection ID: 10031810 | Main Street: MILLENNIUM_AV | Cross Street: SAGE_PARK_DR | Location: | E |
| ADA ID: 1854B0A5E026 | Ramp Type: Directional1 | Initial Pass/Fail: Pass | Overall Compliance: No | Severity Score: 0 |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R305.2

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 53.5 | Yes | Grade Break? | Yes |
| Yes | Ramp Width (in) | 72.0 | Yes | Grade Break Slope (%) | 0.7 |
| Yes | Ramp Slope (%) | 3.0 | Yes | Grade Break XSlope (%) | 1.7 |
| Yes | Ramp XSlope (%) | 1.0 | | | |
| Yes | Flare Type LT | N/A | Yes | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| Yes | Landing Length (in) | 71.0 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 72.0 | Yes | DWS Contrast? | Yes |
| Yes | Landing Slope (%) | 0.2 | Yes | DWS Length (in) | 24.0 |
| Yes | Landing X Slope (%) | 2.0 | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | No | No | DWS Offset LT (in) | 13.0 |
| N/A | Shared Landing? | Yes | Yes | DWS Offset RT (in) | 41.0 |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 4.1 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.4 |
| N/A | Painted X Walk1? | No | | Road Slope (%) | 3.7 |
| | X Walk 1 Direction | To SW | | Road X Slope (%) | 1.2 |
| | X Walk 1 Width (in) | N/A | | Clear Space? | Yes |
| | X Walk 1 Slope (%) | 3.7 | N/A | Clear Space to XWalk (in) | N/A |
| | X Walk 1 X Slope (%) | 1.2 | Yes | Storm Grate/Utility Hazard? | No |
| N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| Yes | Any Obstructions? | No | | | N/A |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | N/A | Curb Slope (%) | 8.9 |

Total Cost: \$ 1600.00

