cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17788 Main St	Main Street: BADWICK DD Creek Street: N.						Location	NE
	Main Street: BARWICK_RD			N_SHARON_AMITY_F	Location:			
ADA ID: 1857B44950B3 Ramp T	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	21.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Da			Comp	Data	
E C C C C C C C C C C C C C C C C C C C	Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	45.5	No	Ramp Slope (%)	11.2
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.3
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
- State			N/A	Shared Landing?	N/A			
A A A A A A A A A A A A A A A A A A A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.5.1,			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	······, ······, ·······		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SE		X Walk 2 Direction	To SW
a that is the state of the second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BARWICK RD	-			X Walk 1 Slope (%)	6.8		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	4.1
Street 2 Name N SHARON AMITY RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	1.8	N/A	Clear Space?	N/A
				Road X Slope (%)	6.7	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

