## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Curb Slope (%)

Good

3.1

			<b>`</b>		. /					
Intersection ID: 48418 Main Street: WINDS_CROSSING_DR C						SOUTH_POINT_BV		Location: SE		
ADA ID: 1873775EC1F8	75EC1F8 Ramp Type: Combination1Diag				Initial Pass/Fail: Fail Overall Compliance:				e: No Severity Score: 0	
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance				
	18 A.	Possible Solutions:			Compliance Description		Data Compliance Description			Data
C 31 12	1 - 1 - 10	Remove & Replace Cu			N/A	Ramp Length LT (in)	68.0	N/A	Ramp Length RT (in)	59.0
		Two New Directional Ramps Equivalent.			Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0
					No	Ramp Slope LT (%)	8.7	Yes	Ramp Slope RT (%)	5.0
					No	Ramp XSlope LT (%)	2.1	Yes	Ramp XSlope RT (%)	1.6
E.					N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	2.8
	DS_GROSSING_DIX	1			Yes	Ramp Width (in)	49.5	Yes	Ramp XSlope (%)	1.6
	FRI	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1 Mart				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	1 1 20 -	R304.3.2, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	WINS CROSSING DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None					X Walk 1 Direction	To N		X Walk 2 Direction	To W
Stop Condition-Street 2	SOUTH POINT BV					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	1.4
						X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	3.8
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	3.1		Clear Space?	N/A
						Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
		. AND A CONTRACT			Sec.			N/A	Any Obstruction?	N/A
					and the second				Obstruction Type	
					and a state of the	in and the				N/A
				and the second	T_M			N/A	Storm Grate/Utility Hazard?	N/A
7						and the second			Storm Grate/Utility Type	107
4		The Property			a sta	to the state of the				N/A
		the second	Tale And Andrews	The second second		Card and a second s		1		- ·