

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2853 Main Str	853 Main Street: CARDINAL_POINT_RD		Cross Street: BENFIELD_RD			Location:	NW
ADA ID: 18A0121C7136 Ramp Ty	7136 Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No			12.5
Codes/Mitigation Info/Possible Solution		Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5 Field Measurements/Component Compliance					
	Possible Solutions:				liance Description	Data	
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	130.0	N/A	Grade Break?	N/A
	·······	Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	0.0
		No	Ramp Slope (%)	8.5	N/A	Grade Break XSlope (%)	0.0
		Yes	Ramp XSlope (%)	1.0			
Contraction of the second seco		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	Surveyor Notes:	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
B.	PROW/ADA:	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	R304.2.2	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No		Road Slope (%)	1.7
Street 1 Name CARDINAL POINT RD			X Walk 1 Direction	To S		Road X Slope (%)	6.9
Stop Condition-Street 1 StopSign			X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name N/A			X Walk 1 Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2 N/A			X Walk 1 X Slope (%)	6.9	N/A	Storm Grate/Utility Hazard?	N/A
		N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
		N/A	Any Obstructions?	N/A			N/A
	Total Cost: \$1	600.00	Obstruction Type		Yes	Surface Condition? (G/P)	Good
				N/A	N/A	Curb Slope (%)	4.0

