## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		-					
Intersection ID: 28092	Main Street: TOM_SHORT_RD			Street:	WARWICK_LINKS_DF	Location:	NW		
ADA ID: 18BA618310CE	Ramp Ty	Ramp Type: PerpDiag Ir			itial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
1 1 1 1 1 1 TH		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	Nith	N/A	Ramp Length (in)	58.0	No	Ramp Slope (%)	9.7
1 - 1 - 1				Yes	Ramp Width (in)	54.0	Yes	Ramp XSlope (%)	0.4
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
1211				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Sector 1.	E AUTEE			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 1 1 1 1 1	the mart			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	E WAS	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A A A A A A A A	Her Contraction	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	the state			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
5 / 2	d.			N/A	Shared Landing?	N/A			
· · / //		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 1 1	18 18 1	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To SE
the second	1 11 200			N/A	X Walk 1 Width (in)	61.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	TOM SHORT RD	-			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	2.6
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	1.7
Street 2 Name	WARWICK LINKS DR			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.8	N/A	Clear Space?	N/A
					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

