cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 10572 Main St | Main Street: GRIMES ST | | reet. | SYLVANIA AV | Location: | W | | |
|--|---|--|---|-----------------------|-----------|-----------------------------|-----------------------------|-------|
| | | | | | | | | |
| ADA ID: 1907EF60CEF2 Ramp Type: PerpDiag | | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 8.75 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
| | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | |
| | Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent. | /ith | N/A | Ramp Length (in) | 49.5 | Yes | Ramp Slope (%) | 7.2 |
| | | | No | Ramp Width (in) | 47.0 | Yes | Ramp XSlope (%) | 1.0 |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | Not Found, R304.5.1 | | N/A | Gutter Lip Ht (in) | 1.0 | N/A | Gutter X Slope (%) | N/A |
| attend of the state of the | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE |
| and the state of t | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name GRIMES ST | _ | | | X Walk 1 Slope (%) | 2.3 | | X Walk 2 Slope (%) | 2.2 |
| Stop Condition-Street 2 StopSign | | | | X Walk 1 X Slope (%) | 0.9 | | X Walk 2 X Slope (%) | 4.3 |
| Street 2 Name SYLVANIA AV | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 None | | | | Road Slope (%) | 3.9 | N/A | Clear Space? | N/A |
| | | | | Road X Slope (%) | 3.8 | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Total Cost: \$ 32 | 200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

