cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

6.5

Good

Surface Condition? (G/P)

Curb Slope (%)

Yes

			· · · · ·		/						
Intersection ID: 17464	Main Stree	Main Street: FALLS_CREEK_LN				SCALEYBARK_RD	Location: S				
ADA ID: 1909B173C92C	Ramp Typ	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			ice: N	o Severity Score:	0	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Statistics -	Prove P	Possible Solutions:			Compliance Description		Data Compliance Description			Data	
	- AR	Remove & Replace C	Curb Ram	p With	N/A	Ramp Length LT (in)	126.0	N/A	Ramp Length RT (in)	58.0	
	NEL	Two New Directional		•	No	Ramp Width LT (in)	34.4	No	Ramp Width RT (in)	34.5	
the states of th	ATTICAL	Equivalent.	-		No	Ramp Slope LT (%)	8.8	Yes	Ramp Slope RT (%)	7.7	
d.	1 at 1				Yes	Ramp XSlope LT (%)	0.5	Yes	Ramp XSlope RT (%)	0.6	
A start and a start and a start a star	LA C				N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	4.0	
					Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.5	
ALLER A	E S	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
MAS &	Real Providence	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
- Carlos - C					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	C 10 H C				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	F	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
Not Found, R304.5.1, R304.3.2					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
the second second	Carlys				N/A	Shared Landing?	N/A				
The second states of the					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	SCALEYBARK RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	None					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
Stop Condition-Street 2	FALLS CREEK LN					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	1.2	
						X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	5.1	
	1	lotal Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	3.7		Clear Space?	N/A	
						Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A	
				100	San Maria			N/A	Any Obstruction?	N/A	
									Obstruction Type		
										N/A	
	Caller manager							N/A	Storm Grate/Utility Hazard?	NI/A	
				10					Storm Grate/Utility Type	N/A	
				C. C.L.	- Aller and a second			I	5 51		

