## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22391	Main Str	Cross	Cross Street: WHISTLESTOP_RD				Location:	S	
ADA ID: 1918E78731A5	Ramp T	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance:			o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:							Data
de la companya de la comp		Remove & Replace Curb Ram	n With	N/A	Ramp Length (in)	59.0	Yes	Ramp Slope (%)	5.8
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	14.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
and the second s				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A Real of a			N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
	a maximum			N/A	Shared Landing?	N/A		( )	
	the A	PROW/ADA:		N/A	Gutter Ponding?		N/A	Gutter Slope (%)	N/A
	Sharely The States	Not Found, R304.5.1, R304.5.	2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A AME	NOL FOUND, N304.5.1, N304.5.	5	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	And A start			N/A	X Walk 1 Direction	To NE		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name WHISTLESTOP RD				11/4	X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	5.7
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5. <del>9</del> 6.4		X Walk 2 Slope (%)	5.7 6.9
Steet 2 Name				NI/A	• • • •			• • • •	
	SHARON RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	10.8	N/A	Clear Space?	N/A
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

