

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17926 Main Street: N_SHARON_AMITY_RD **Cross Street: RANDOLPH RD** Location: NW ADA ID: 1974C770E2EE Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 25

Codes/Mitigation Info/Possible Solution



Street 1 Name N SHARON AMITY RD Stop Condition-Street 2 Signal Street 2 Name **RANDOLPH RD** Stop Condition-Street 1 Signal Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

Total Cost: 3200.00

Field Measurements/Component Compliance						
Compl	iance Description	Data	Compl	iance	Description	Data
N/A	Ramp Length (in)	60.0	No	Ramp	Slope (%)	17.8
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	0.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	Yes
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	To E
N/A	X Walk 1 Width (in)	112.0	N/A	X Wa	lk 2 Width (in)	109.0
	X Walk 1 Slope (%)	2.6		X Wa	lk 2 Slope (%)	7.6
	X Walk 1 X Slope (%)	4.3		X Wa	lk 2 X Slope (%)	0.2
N/A	Ramp inside XWalk1?	Yes	N/A	Ram	o inside XWalk2?	Yes
	Road Slope (%)	0.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	4.8	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
				Surfa	ce Condition? (G/P)	Good





