cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			<u> </u>	,					
Intersection ID: 10038262	ection ID: 10038262 Main Street: SMITH_RD				N/A	Location:	SW		
ADA ID: 197D1C031504 Ramp Type: PerpDiag				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	47.5	No	Ramp Slope (%)	12.4
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	4.3
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To E		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	120.0
Street 1 Name	SMITH RD				X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	0.8
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	None				Road Slope (%)	1.9	N/A	Clear Space?	N/A
					Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
i de la constante de									

Yes Surface Condition? (G/P)

Good

