


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 12082	Main Street: ALLEN_ST	Cross Street: E_16TH_ST	Location: E
ADA ID: 1981993A543A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
<p>Surveyor Notes:</p> <p>N/A</p>			N/A	Ramp Length (in)	52.0
			No	Ramp Width (in)	38.5
<p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2</p>			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
<p>Total Cost:</p> <p>\$ 3200.00</p>			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NW
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.6
				X Walk 1 X Slope (%)	6.0
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	0.6
				Road X Slope (%)	4.8
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
					N/A
			Yes	Surface Condition? (G/P)	Good

