

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 19862		Main Street: EASTHAM_LN		Cross Street: WINTERCREST_LN		Location:		NW	
ADA ID: 198ABCF92667		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 2.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
 Possible Solutions: Remove & Replace Entire Ramp. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.1.4, R305.2 Street 1 Name EASTHAM LN Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A Total Cost: \$ 2350.00				Compliance	Description	Data	Compliance	Description	Data
				N/A	Ramp Length (in)	32.0	Yes	Grade Break?	Yes
				Yes	Ramp Width (in)	56.0	Yes	Grade Break Slope (%)	3.3
				Yes	Ramp Slope (%)	3.3	No	Grade Break XSlope (%)	3.3
				Yes	Ramp XSlope (%)	1.9			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				No	Landing Length (in)	35.0	Yes	DWS Provided?	Yes
				Yes	Landing Width (in)	57.0	Yes	DWS Contrast?	Yes
				No	Landing Slope (%)	7.1	Yes	DWS Length (in)	24.5
				No	Landing X Slope (%)	4.0	No	DWS Full Width?	No
				N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	68.0
				N/A	Shared Landing?	No	No	DWS Offset RT (in)	5.0
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.8
				Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.4
				N/A	Painted X Walk1?	No		Road Slope (%)	6.6
					X Walk 1 Direction	To SE		Road X Slope (%)	1.4
					X Walk 1 Width (in)	N/A		Clear Space?	Yes
					X Walk 1 Slope (%)	6.6	N/A	Clear Space to XWalk (in)	N/A
					X Walk 1 X Slope (%)	1.4	Yes	Storm Grate/Utility Hazard?	No
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				Yes	Any Obstructions?	No			N/A
					Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	Curb Slope (%)	0.6

