

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			`		,					
Intersection ID: N/A	Main Street: LEWIS_ST				eet:	CLARK_BV	Location:	SW		
ADA ID: 1A06EBCFDBCB	Ramp T	Initial Pass/Fail: Fail Overall Compliance				nce: N	o Severity Score:	1.25		
Codes/M	litigation Info	/Possible Solution				Field Measuren	nents/C	ompo	nent Compliance	
	A MAR	Possible Solutions:		Compliance Description		Data	Comp	liance Description	Data	
	themas I	Remove & Replace I	Entire Ramp.	N	I/A	Ramp Length LT (in)	55.0	N/A	Ramp Length RT (in)	37.0
		Remove & Replace		۲	'es	Ramp Width LT (in)	64.0	Yes	Ramp Width RT (in)	64.0
No.		£		۲	'es	Ramp Slope LT (%)	1.5	Yes	Ramp Slope RT (%)	5.9
	3			N	lo	Ramp XSlope LT (%)	2.3	Yes	Ramp XSlope RT (%)	0.9
		7		N	A/A	Ramp Length (in)	64.0	Yes	Ramp Slope (%)	1.6
	A ALLAND			۱	/es	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.3
		Surveyor Notes:		١	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	NI CO	N/A		N	A/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
9		2		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	19			N	A/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
- And	- P			N	A/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A STORY	PROW/ADA:		N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.5.3		N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1. 1. 3				I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The			N	I/A	Shared Landing?	N/A			
	Provent and			١	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign			Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	LEWIS ST			M	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 22	00.00	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	28 - C.S.		1		5 7 3	dahimatike		N/A	Any Obstruction?	N/A
					And And And				Obstruction Type	
					1					N/A
	1					S.S. AL		N/A	Storm Grate/Utility Hazard?	N/A
				and the second second					Storm Grate/Utility Type	11/2
					-					N/A
		the test			A CALLER OF			I		. .







Yes

Surface Condition? (G/P)

Curb Slope (%)

Good

20.2