

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: ARDREY_KELL_DR Cross Street: VILLAGE_WALK_DR Location: SE Ramp Type: Directional1 **Overall Compliance: No** ADA ID: 1A4A61A2AE55 Initial Pass/Fail: Fail **Severity Score:** 1.25

Codes/Mitigation Info/Possible Solution



Street 1 Name **VILLAGE WALK DR** Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:							
Remove & Replace Entire Ramp.							
Surveyor Notes:							
N/A							
PROW/ADA:							
R304.5.3							

PROW/ADA:			ı
R304.5.3			ı
			ı
			ı
			ı
T. 1.0. 1	•	4000.00	
Total Cost:	\$	1600.00	

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A			
Yes	Ramp Width (in)	95.0	N/A	Grade Break Slope (%)	0.0			
Yes	Ramp Slope (%)	6.2	N/A	Grade Break XSlope (%)	0.0			
No	Ramp XSlope (%)	3.7						
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	Yes		Road Slope (%)	2.0			
	X Walk 1 Direction	To W		Road X Slope (%)	1.9			
	X Walk 1 Width (in)	95.0		Clear Space?	N/A			
	X Walk 1 Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	1.9	N/A	Storm Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type				
N/A	Any Obstructions?	N/A			N/A			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good			
		N/A	N/A	Curb Slope (%)	12.3			





