


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                            |                          |                        |
|------------------------|----------------------------|--------------------------|------------------------|
| Intersection ID: 20526 | Main Street: ARROWCREEK_DR | Cross Street: S_TRYON_ST | Location: NE           |
| ADA ID: 1A53C684EE7C   | Ramp Type: PerpDiag        | Initial Pass/Fail: Fail  | Overall Compliance: No |
|                        |                            | Severity Score: 22.5     |                        |

| Codes/Mitigation Info/Possible Solution  |   |                   | Field Measurements/Component Compliance |                             |             |
|--|---|-------------------|---|-----------------------------|-------------|
|  | Possible Solutions:   |                   | <b>Compliance</b>                       | <b>Description</b>          | <b>Data</b> |
|  | <b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b> |                   | <b>No</b>                               | Ramp Length (in)            | <b>65.0</b> |
|  |   |                   | <b>No</b>                               | Ramp Width (in)             | <b>42.0</b> |
|  |   |                   | <b>N/A</b>                              | Flare Type LT               | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Flare Slope LT (%)          | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Flare Traversable LT?       | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Landing Length (in)         | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Landing Width (in)          | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Landing Slope (%)           | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Landing X Slope (%)         | <b>N/A</b>  |
| <p>Surveyor Notes:</p> <p><b>N/A</b></p>   |   |                   | <b>N/A</b>                              | Flare Type RT               | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Flare Slope RT (%)          | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Flare Traversable RT?       | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | DWS Provided?               | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | DWS Contrast?               | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | DWS Length (in)             | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | DWS Full Width?             | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | DWS Offset (in)             | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Gutter Ponding?             | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Gutter Lip Ht (in)          | <b>N/A</b>  |
| <p>PROW/ADA:</p> <p><b>Not Found, R304.5.1, R304.2.2, R304.5.3</b></p>           |   |                   | <b>No</b>                               | Painted X Walk2?            | <b>No</b>   |
|  |   |                   | <b>To W</b>                             | X Walk 2 Direction          | <b>To S</b> |
|  |   |                   | <b>N/A</b>                              | X Walk 2 Width (in)         | <b>N/A</b>  |
|  |   |                   | <b>3.6</b>                              | X Walk 2 Slope (%)          | <b>2.6</b>  |
|  |   |                   | <b>4.3</b>                              | X Walk 2 X Slope (%)        | <b>4.9</b>  |
|  |   |                   | <b>N/A</b>                              | Ramp inside XWalk2?         | <b>N/A</b>  |
|  |   |                   | <b>3.6</b>                              | Clear Space?                | <b>N/A</b>  |
|  |   |                   | <b>3.5</b>                              | Clear Space to XWalk (in)   | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Storm Grate/Utility Hazard? | <b>N/A</b>  |
|  |   |                   | <b>N/A</b>                              | Storm Grate/Utility Type    | <b>N/A</b>  |
| Total Cost:  |   | <b>\$ 3200.00</b> |   |                             |             |
|  |   |                   | <b>N/A</b>                              | Surface Condition? (G/P)    | <b>Good</b> |

