

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.7

2.1

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 45155 Main Street: SHAD CT Cross Street: MAGNASCO LN Location: N **Overall Compliance: No** 10 ADA ID: 1AAD386F1FFC Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Data

48.0

47.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Flare Traversable LT?



SHAD CT Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

ossible Solution		Field Me
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	No	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.5.1	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk
		Road Slope (%)

9-11	

Total Cost:





N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To SW X Walk 2 Direction N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 2.6 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 3.8 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A N/A N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type 1850.00 N/A N/A Yes Surface Condition? (G/P) Good