

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		`	1 /						
Intersection ID: N/A	tersection ID: N/A Main Street: OLD_PINEVILLE_RD			et: N/A	Location:	SE			
ADA ID: 1ADD77B984EB	7B984EB Ramp Type: Perp			/Fail: Fail	o Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Data Compli			liance Description	Data		
		Remove & Replace Entire Ramp.			₋ength (in)	127.0	No	Ramp Slope (%)	8.7
			Yes		Nidth (in)	69.0	Yes	Ramp XSlope (%)	0.3
			N/A	•		N/A	N/A	Flare Type RT	N/A
	instead of		N/A	Flare S	lope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare T	raversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A		g Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:	N/A		g Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	N/A		g Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing	g X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A		g Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A		Landing?	N/A			
		PROW/ADA:	N/A	Gutter	Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2	N/A	Gutter I	Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted	X Walk1?	Yes	N/A	Painted X Walk2?	N/A
				X Walk	1 Direction	To E		X Walk 2 Direction	N/A
			N/A	X Walk	1 Width (in)	87.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE			X Walk	1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None			X Walk	1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp i	nside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road S	lope (%)	N/A	N/A	Clear Space?	N/A
				Road X	Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Ob	structions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstrue	ction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

