

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

53.0

54.0

3.9

N/A

6.4

Good

Intersection ID: 6243 Main Street: BEATTIES\_FORD\_RD Cross Street: OLDE\_ENGLISH\_DR Location: SE

ADA ID: 1B147D9DDBC2 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Compliance Description

N/A

Yes

Yes

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance

N/A

Yes

Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Data

53.0

54.0

6.5



Street 1 Name
StopSign
Stop Condition-Street 1
OLDE ENGLISH DR
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost:



1800.00

Ramp XSlope LT (%) 4.4 No Ramp XSlope RT (%) No 3.1 N/A Ramp Length (in) 49.0 Nο Ramp Slope (%) 10.6 42.5 No Ramp XSlope (%) No Ramp Width (in) 4.7 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A N/A Painted X Walk1? No Painted X Walk2? N/A To N X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 2.9 X Walk 2 Slope (%) N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 2.1 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type

Yes

Surface Condition? (G/P)

Curb Slope (%)

