


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12241	Main Street: N_SHARON_AMITY_RD	Cross Street: SHARON_CHASE_DR	Location: N
ADA ID: 1B24D0634278	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 36.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	Compliance
	Remove & Replace Entire Ramp.		No	Ramp Length (in)	59.5	No
			No	Ramp Width (in)	40.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R302.7</p>			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	0.5	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To SW	
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	2.0	
				X Walk 1 X Slope (%)	6.1	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Total Cost: \$ 1850.00</p>			N/A	Road Slope (%)	N/A	N/A
				Road X Slope (%)	N/A	N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		
					N/A	N/A
			No	Surface Condition? (G/P)		Poor

