

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13402	Main Street: S_MINT_ST	Cross Street: SPRUCE_ST	Location: N
ADA ID: 1B3854F364DA	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 15.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Grind Gutter Lip.

Surveyor Notes:

LT SL < 5%

PROW/ADA:

R304.5.3, R304.2.2-Perp, R304.3.2-Para, R302.7.2

Street 1 Name	SPRUCE ST
Stop Condition-Street 1	StopSign
Street 2 Name	S MINT ST
Stop Condition-Street 2	None

Total Cost: \$ 3400.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	88.0	N/A	Ramp Length RT (in)	71.0
Yes	Ramp Width LT (in)	68.0	Yes	Ramp Width RT (in)	88.0
Yes	Ramp Slope LT (%)	4.5	Yes	Ramp Slope RT (%)	5.1
No	Ramp XSlope LT (%)	2.1	No	Ramp XSlope RT (%)	2.7
Yes	Landing Length (in)	88.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	61.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	2.1	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.8	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	Yes	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.8
No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	0.3
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	5.4
	X Walk 1 X Slope (%)	5.1		X Walk 2 X Slope (%)	2.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.7	N/A	Clear Space?	Yes
	Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	13.2

