cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17596	Main Street: WATER_OAK_RD		Cross Street: N_SHARON_AMITY_RD					Location:	NW
ADA ID: 1B49181F0EA3	Ramp Ty	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
t.		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	5.4
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	10 493			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A STATE OF THE STA		4		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	CHAR CONTRACTOR	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	192	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
The state of the s				N/A	Shared Landing?	N/A			
N.S.		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 1 S. Mar	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
//	Land L			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
11 385 1					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	N SHARON AMITY RD				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	5.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	5.4		X Walk 2 X Slope (%)	5.3
Street 2 Name	WATER OAK RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.2	N/A	Clear Space?	N/A
					Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

