

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11428 Main Street: THE PLAZA **Cross Street: DUNCAN AV** Location:

ADA ID: 1B527E7103E7 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 58.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



DUNCAN AV Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A R304.5.1, R304.2.2, R304.5.3

PROW/ADA: Total Cost: 1850.00

Compl	iance Description	Data	Compl	ance Description	n Data
N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	15.0
No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	8.7
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%) N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable	RT? N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%) N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in	n) N/A
	X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%	(a) N/A
	X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope	(%) N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWa	lk2? N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XV	Valk (in) N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility	Hazard? N/A
	Obstruction Type			Storm Grate/Utility	<i>т</i> Туре
		N/A			N/A
			Yes	Surface Condition	? (G/P) Good





