cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10017066 Main Street: NEAL_RD Cross S				N/A			Location:	NE
			Initial Pass/Fail: Fail Overall Compliance: No				42.5	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:						liance Description	Data
	Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.	-	/A	Ramp Length (in)	130.0	No	Ramp Slope (%)	9.1
		N		Ramp Width (in)		No	Ramp XSlope (%)	5.2
		Ν	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N	/ A	Shared Landing?	N/A			
	PROW/ADA:	N	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2, R304.5.3	Ν	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N	/ A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To W		X Walk 2 Direction	To S
		N	/ A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name NEAL RD				X Walk 1 Slope (%)	8.7		X Walk 2 Slope (%)	6.9
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	7.1
Street 2 Name ENTRANCE		N	/ A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	5.1	N/A	Clear Space?	N/A
				Road X Slope (%)	9.0	N/A	Clear Space to XWalk (in)	N/A
		Ν	/ A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P) Good

