

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

4.1

5.4

N/A

No

N/A

0.5

3.4

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 9.5

To SW

Intersection ID: 17945 Main Street: E WOODLAWN RD **Cross Street: MURRAYHILL RD** Ε Location: **Overall Compliance: No Severity Score:** 0 ADA ID: 1BAD86169D81 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign MURRAYHILL RD None E WOODLAWN RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost: 3200.00 Compliance Description Data Compliance Description N/A N/A Ramp Length LT (in) 53.0 Ramp Length RT (in) N/A Yes Ramp Width LT (in) 53.0 Ramp Width RT (in) 13.2 N/A No Ramp Slope LT (%) Ramp Slope RT (%) Ramp XSlope LT (%) N/A Ramp XSlope RT (%) Yes 1.1 N/A Ramp Length (in) 36.0 Yes Ramp Slope (%) 42.0 No Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To NW X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 4.0 X Walk 1 Slope (%) X Walk 2 Slope (%)

5.0

N/A

5.8

0.2

N/A

N/A

N/A

N/A

Yes

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)







N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)