

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data 13.0 0.5 N/A N/A N/A N/A N/A N/A N/A N/A

> N/A N/A N/A N/A N/A

> N/A

N/A

N/A

N/A N/A N/A

N/A

Good

Intersection ID: 4672 Main Street: W_MALLARD_CREEK_CHURCIERSS Street: SENATOR_ROYALL_DR Location: NW **ADA ID: 1BB4C670BC4D** Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 25

Codes/Mitigation Info/Po

Yes

Surface Condition? (G/P)



MALLARD CREEK CHURCH RD Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

/Possible Solution Field Measurements/Component Complia					Compliance
Possible Solutions:	Comp	oliance Description	Data	Compliance	Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	102.0	No Ran	np Slope (%)
· ·	Yes	Ramp Width (in)	48.0	Yes Ran	np XSlope (%)
	N/A	Flare Type LT	N/A	N/A Flar	e Type RT
	N/A	Flare Slope LT (%)	N/A	N/A Flar	e Slope RT (%)
	N/A	Flare Traversable LT?	N/A	N/A Flar	e Traversable RT?
	N/A	Landing Length (in)	N/A	N/A DW	S Provided?
Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A DW	S Contrast?
N/A	N/A	Landing Slope (%)	N/A	N/A DW	S Length (in)
	N/A	Landing X Slope (%)	N/A	N/A DW	S Full Width?
	N/A	Landing Curb? (Y/N)	N/A	N/A DW	S Offset (in)
	N/A	Shared Landing?	N/A		
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A Gut	ter Slope (%)
R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A Gut	ter X Slope (%)
	N/A	Painted X Walk1?	Yes	N/A Pair	nted X Walk2?
		X Walk 1 Direction	To SW	ΧW	alk 2 Direction
	N/A	X Walk 1 Width (in)	104.0	N/A X W	/alk 2 Width (in)
		X Walk 1 Slope (%)	10.0	ΧW	/alk 2 Slope (%)
		X Walk 1 X Slope (%)	4.0	ΧW	/alk 2 X Slope (%)
	N/A	Ramp inside XWalk1?	Yes	N/A Rar	np inside XWalk2?
		Road Slope (%)	N/A	N/A Clea	ar Space?
		Road X Slope (%)	N/A	N/A Clea	ar Space to XWalk (in)
	N/A	Any Obstructions?	N/A	N/A Sto	m Grate/Utility Hazard?
Total Cost: \$ 1850.00)	Obstruction Type		Sto	m Grate/Utility Type
			N/A		





