

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 9413 Main Street: BODKIN_CT		Cross Street: CAMBRIDGE_COMMONS_DR				Location:	NE
ADA ID: 1BB71B93D563 Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
the set of	Possible Solutions:	Compliance Description Date			a Compliance Description		Data
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.0
Wet &	×	No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.0
CINTERIDER CONTROLE DRA CONTERIDER CONTROLE DRA CONTERIDER CONTROLE DRA CONTERIDER CONTROLE DRA		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	day.	N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.5.1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To E		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CAMBRIDGE COMMONS DR	1		X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Non	•		X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$1	850.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

