


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|--------------------------|--------------------------|------------------------|
| Intersection ID: 15564 | Main Street: CHEROKEE_RD | Cross Street: COTTAGE_PL | Location: NW |
| ADA ID: 1BC2E7149F35 | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 25 | |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|--|---|--|---|-----------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | No | Ramp Length (in) | 46.0 |
| | | | Yes | Ramp Width (in) | 96.0 |
| | | | N/A | Flare Type LT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A |
| | | | N/A | Landing Length (in) | N/A |
| | | | N/A | Landing Width (in) | N/A |
| | | | N/A | Landing Slope (%) | N/A |
| | | | N/A | Landing X Slope (%) | N/A |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p> | | | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable RT? | N/A |
| | | | N/A | DWS Provided? | N/A |
| | | | N/A | DWS Contrast? | N/A |
| | | | N/A | DWS Length (in) | N/A |
| | | | N/A | DWS Full Width? | N/A |
| | | | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A |
| | | | N/A | Gutter Ponding? | N/A |
| <p>Total Cost:</p> <p>\$ 3200.00</p> | | | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk1? | No |
| | | | No | Painted X Walk2? | No |
| | | | To SW | X Walk 2 Direction | To E |
| | | | N/A | X Walk 2 Width (in) | N/A |
| | | | 8.2 | X Walk 2 Slope (%) | 1.6 |
| | | | 0.2 | X Walk 2 X Slope (%) | 7.8 |
| | | | N/A | Ramp inside XWalk2? | N/A |
| | | | 5.3 | Clear Space? | N/A |
| | | | 6.0 | Clear Space to XWalk (in) | N/A |
| | | | N/A | Any Obstructions? | N/A |
| | | | N/A | Obstruction Type | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | N/A | Storm Grate/Utility Type | N/A |
| | | | N/A | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

