

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27	7422 Main St	eet: BALLANTYNE_COMMONS_PY Cross Street: STONEBRIAR_DR						Location:	NE	
ADA ID: 1BD74AE29509 Ramp Ty		ype: Perp	Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	42.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	Carl Barris 1 1 + 1	Possible Solutions:		Compliance Description Da			ata Compliance Description		Data	
		Remove & Replace Entire Ram	ip.	N/A	Ramp Length (in)	110.0	No	Ramp Slope (%)	9.2	
			•	No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	5.6	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A States	A PARTY A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
S The				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
<u>د.</u>		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
~ ~				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	BALLANTYNE COMMONS PY			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
The second second second		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
C. C.		Not Found, R304.5.1, R304.2.2, R304.5.3	)	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A Contraction		,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	19- a la st				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
	1/4 3 4 9 8 10			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	BALLANTYNE COMMONS PY				X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

es Surface Condition? (G/P)

Good

