cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50589	Main Str	eet: BENDING_BR	RANCH_RD	Cross Street: GREEN_GRASS_RD				Location:	NW
ADA ID: 1BFE67B5A1F0	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description Da		
		Remove & Repla	ace Entire Ramp.	N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	6.0
				No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	4.5
A Start Star				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E CAN	11/10			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	A AND			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
VEEK	S			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
COLOR COLOR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ROL B		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E. St				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	A A B	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A AL	Not Found, R30	451 R30453	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N. / S.S.		4.0.1, 1004.0.0	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	A MAN				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
De Martin	A state to			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GREEN GRASS RD				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	350.00	Obstruction Type			Storm Grate/Utility Type	
			¥ N			N/A			N/A
						17/5			10/5

Yes Surface Condition? (G/P)

Good





