

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8380 Main Street: CENTRE ST **Cross Street: TENNESSEE AV** Location: ADA ID: 1C6005C6A8F9 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Field Measurements/Component Compliance

Codes/Mitigation Info/Possible Solution Surveyor Notes:

Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

PROW/ADA: Not Found, R304.5.1, R304.5.3

CENTRE ST StopSign **TENNESSEE AV** None

N/A

Total Cost: 3200.00

Field Measurements/Component Compliance								
	Compl	Compliance Description			Compliance		Description	Data
	N/A	Ramp	Length (in)	108.0	Yes	Ramp	Slope (%)	6.2
	No	Ramp	Width (in)	44.0	No	Ramp	XSlope (%)	6.6
	N/A	Flare	Type LT	N/A	N/A	Flare	Type RT	N/A
	N/A	Flare	Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
	N/A	Flare	Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
	N/A	Landi	ng Length (in)	N/A	N/A	DWS	Provided?	N/A
	N/A	Landi	ng Width (in)	N/A	N/A	DWS	Contrast?	N/A
	N/A	Landi	ng Slope (%)	N/A	N/A	DWS	Length (in)	N/A
	N/A	Landi	ng X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
	N/A	Landi	ng Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
	N/A	Share	ed Landing?	N/A				
	N/A	Gutte	er Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
	N/A	Gutte	r Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
	N/A	Painte	ed X Walk1?	No	N/A	Painte	ed X Walk2?	No
		X Wa	lk 1 Direction	To SE		X Wa	lk 2 Direction	To NE
	N/A	X Wa	lk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
		X Wa	lk 1 Slope (%)	3.3		X Wa	lk 2 Slope (%)	3.1
		X Wa	lk 1 X Slope (%)	2.8		X Wa	lk 2 X Slope (%)	1.9
	N/A	Ramp	inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
		Road	Slope (%)	2.8	N/A	Clear	Space?	N/A
		Road	X Slope (%)	0.5	N/A	Clear	Space to XWalk (in)	N/A
	N/A	Any C	Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
		Obstr	ruction Type			Storm	n Grate/Utility Type	
				N/A				N/A
					Yes	Surfa	ce Condition? (G/P)	Good





