

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3112 Mair	Main Street: LANAKEN_DR		Cross Street: WALDEN_RIDGE_DR			Location: N			
	Ramp Type: Directional1		Initial Pass/Fail: Fail Overall Co			ompliance: No Severity			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:		C	Compliance Description Data Compliance Description Data						
A PART AND A PART	Remove & Replace Entire Ram	_	1/A	Ramp Length (in)	34.0	N/A	Grade Break?	N/A	
			10	Ramp Width (in)	44.0	N/A	Grade Break Slope (%)	0.0	
	A MAR		'es	Ramp Slope (%)	6.1	N/A	Grade Break XSlope (%)	0.0	
			lo	Ramp XSlope (%)	6.7				
	and the second se		I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	Surveyor Notes:		I/A	Flare Traversable LT?		N/A	Flare Traversable RT?	N/A	
	N/A	Ν	I/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
WALDENLRIDGELDR		Ν	I/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
			I/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	Mar.		I/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	PROW/ADA:	Ν	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	R304.5.1, R304.5.3	Ν	I/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
- AL ALANDAR A	1004.0.1, 1004.0.0		I/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
AL ACTION TO A	7		I/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
		Ν	I/A	Painted X Walk1?	No		Road Slope (%)	3.7	
Street 1 Name WALDEN RIDGE	DR			X Walk 1 Direction	To S		Road X Slope (%)	2.2	
Stop Condition-Street 1	ne			X Walk 1 Width (in)	N/A		Clear Space?	N/A	
	I/A			X Walk 1 Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	I/A			X Walk 1 X Slope (%)	2.2	N/A	Storm Grate/Utility Hazard?	N/A	
		Ν	I/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
			I/A	Any Obstructions?	N/A			N/A	
	Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
					N/A	N/A	Curb Slope (%)	27.2	

