


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 51630	Main Street: STEELECROFT_PY	Cross Street: CLOISTERS_CLUB_LN	Location: SE
ADA ID: 1CCA7A221436	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 <p>Street 1 Name CLOISTERS CLUB LN</p> <p>Stop Condition-Street 1 StopSign</p> <p>Street 2 Name N/A</p> <p>Stop Condition-Street 2 N/A</p>	Possible Solutions:	Remove & Replace Entire Ramp.			
	Surveyor Notes:	N/A			
	PROW/ADA:	R304.5.3			
			Compliance	Description	Data
			N/A	Ramp Length (in)	48.0
			Yes	Ramp Width (in)	59.0
			Yes	Ramp Slope (%)	1.6
			No	Ramp XSlope (%)	3.8
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	0.0
			N/A	Landing Width (in)	0.0
			N/A	Landing Slope (%)	0.0
			N/A	Landing X Slope (%)	0.0
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	0.0
			N/A	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To N
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.6
				X Walk 1 X Slope (%)	0.7
			N/A	Ramp inside XWalk1?	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	13.4
Total Cost:		\$ 1600.00			

