

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 2988	Main Street: WAVERLY LYNN LN	Cross Street: THOMAS RIDGE DR	Location: NW
ADA ID: 1D5FB61465D5	Ramp Type: BlendTrans1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 22.5	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305, R302.7.2, R304.5.4, R304.5.3

Total Cost: \$ 3950.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	84.0	Yes	BlendTrans Slope (%)	3.5
Yes	Ramp Width (in)	132.0	Yes	BlendTrans XSlope (%)	1.2
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	5.3	N/A	Flare Slope RT (%)	6.8
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
No	Landing Length (in)	45.0	No	DWS Provided?	No
Yes	Landing Width (in)	108.0	N/A	DWS Contrast?	No
No	Landing Slope (%)	2.4	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	0.6	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	8.2
No	Gutter Lip Ht (in)	0.3	No	Gutter X Slope (%)	2.2
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	5.0
	X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	4.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.0		Clear Space?	Yes
	Road X Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			No	Curb Slope (%)	6.6

Street 1 Name THOMAS RIDGE DR
 Stop Condition-Street 1 StopSign
 Street 2 Name WAVERLY LYNN LN
 Stop Condition-Street 2 None

