

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22954 Main Street: ARBOR\_RIDGE\_DR Cross Street: IVEY\_CREEK\_DR Location: NE

ADA ID: 1D906EE13CA6 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 ARBOR RIDGE DR StopSign IVEY CREEK DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

N

Surveyor Notes:

N/A

N

PROW/ADA:

Not Found, R304.5.3

N

Total Cost: \$ 3200.00

Field Measurements/Component Compliance					
Compliance Description		Data	Com	oliance Description	Data
N	A Ramp Length (in)	44.0	Yes	Ramp Slope (%)	5.8
Y	es Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8
N	A Flare Type LT	N/A	N/A	Flare Type RT	N/A
N	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N	A Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N	A Shared Landing?	N/A			
N	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N	A Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N	A Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
N	A X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	0.7
	X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	2.7
N	A Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	2.9	N/A	Clear Space?	N/A
	Road X Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
N	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
u r	The same of the sa				





