

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 14091 Main Street: E\_7TH\_ST Cross Street: N\_CASWELL\_RD Location: SE **Overall Compliance: No Severity Score:** ADA ID: 1DB4E72BD7A0 Ramp Type: Perp Initial Pass/Fail: Fail 12.5

**Codes/Mitigation Info/Possible Solution** 



E 7TH ST Street 1 Name Signal Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

OSSIDIE SOIGHOII	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
	Ye
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.3	N/A
	N/A
	N/A
	N/A

1		
1		
	19.00	



Total Cost:



1850.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	oliance	Description	Data		
N/A	Ramp Length (in)	114.0	Yes	Ram	Slope (%)	7.1		
Yes	Ramp Width (in)	48.0	No	Ram	XSlope (%)	5.2		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To NE		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	94.0	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.0		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.0		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ram	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		

Yes

Surface Condition? (G/P)

Good