cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11843	Main Street: CLARK_ST			Cross	Cross Street: COUNTRY_CLUB_DR				Location:	NW	
ADA ID: 1DF7D0485BA7	Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	35	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	A BARRA	Possible Solutions:		Compliance Description			Data Compliance Description				
		Remove & Replace Er	tire Ram	o .	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	16.2	
				-	No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	2.4	
	AN AN AND				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Anna and				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
States and States	For the se				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
COUNTRA COLUE DE		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	Part .	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	81 33				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	/ 3				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Charles -	and the				N/A	Shared Landing?	N/A				
BADE		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The second second		Not Found, R304.5.1, R304	R304 2 2		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
april and the second		R304.5.3	1.004.2.2,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
the second second	5/100				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	CLARK ST	•				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	4.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	. c N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
			·			<i>,</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N/A			N/A	

Yes Surface Condition? (G/P)

Good

