


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5066	Main Street: IBM_DR	Cross Street: OLD_MALLARD_CREEK_RD	Location: NW
ADA ID: 1E1CB82C1388	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 48.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	Compliance
	Remove & Replace Entire Ramp.		No	Ramp Length (in)	48.0	No
			No	Ramp Width (in)	46.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2, R302.7</p>			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	N/A	N/A
			N/A	Flare Traversable RT?	N/A	N/A
			N/A	DWS Provided?	N/A	N/A
			N/A	DWS Contrast?	N/A	N/A
			N/A	DWS Length (in)	N/A	N/A
			N/A	DWS Full Width?	N/A	N/A
			N/A	DWS Offset (in)	N/A	N/A
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
<p>Total Cost:</p> <p>\$ 1850.00</p>			No	Painted X Walk1?	No	N/A
			N/A	X Walk 1 Direction	To S	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A
			0.3	X Walk 1 Slope (%)	0.3	N/A
			5.8	X Walk 1 X Slope (%)	5.8	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A
			N/A	Road Slope (%)	N/A	N/A
			N/A	Road X Slope (%)	N/A	N/A
			N/A	Any Obstructions?	N/A	N/A
			N/A	Obstruction Type		N/A
			N/A	Storm Grate/Utility Hazard?	N/A	N/A
			No	Storm Grate/Utility Type		N/A
			No	Surface Condition? (G/P)		Poor

