

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4167Main Street:CLAUDE_FREEMAN_DRCross Street:W_MALLARD_CREEK_CHURCH_RDLocation:NADA ID: 1E6282C8DC4DRamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution



Street 1 Name MALLARD CREEK CHURCH RD
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

POSSIBLE SOLUTION	
Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	N
·	Y
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
R304.2.2	N
	N
	N
	N
	N





Total Cost:



1850.00

Field Measurements/Component Compliance						
Compliance Description Data		Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	13.0	
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.0	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	103.0	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	