


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10033959	Main Street: PARK_RD	Cross Street: N/A	Location: SE
ADA ID: 1E7C12331192	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 13.75			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:						
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.						
	Surveyor Notes:						
	N/A						
	PROW/ADA:						
	Not Found, R304.2.2, R304.5.3						
				Compliance	Description	Data	Compliance
				Description			Description
				Data			Data
Street 1 Name	ENTRANCE				N/A	Ramp Length (in)	58.0
Stop Condition-Street 2	StopSign				Yes	Ramp Width (in)	48.0
Street 2 Name	PARK RD				N/A	Flare Type LT	N/A
Stop Condition-Street 1	None				N/A	Flare Slope LT (%)	N/A
					N/A	Flare Traversable LT?	N/A
					N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable RT?	N/A
					N/A	DWS Provided?	N/A
					N/A	DWS Contrast?	N/A
					N/A	DWS Length (in)	N/A
					N/A	DWS Full Width?	N/A
					N/A	DWS Offset (in)	N/A
					N/A	Gutter Ponding?	N/A
					N/A	Gutter Lip Ht (in)	N/A
					N/A	Painted X Walk1?	No
						X Walk 1 Direction	To N
					N/A	X Walk 1 Width (in)	N/A
						X Walk 1 Slope (%)	0.4
						X Walk 1 X Slope (%)	3.0
					N/A	Ramp inside XWalk1?	N/A
						Road Slope (%)	2.0
						Road X Slope (%)	2.0
					N/A	Any Obstructions?	N/A
						Obstruction Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3200.00

