


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10361	Main Street: CHAMBERLAIN_AV	Cross Street: S_TURNER_AV	Location:	W
ADA ID: 1E9888B817E6	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 42.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance										
	Possible Solutions:		Compliance			Description			Data				
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		49.0		No	Ramp Slope (%)		8.6		
			No	Ramp Width (in)		33.0		No	Ramp XSlope (%)		6.2		
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A		
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A		
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A		
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A		
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A		
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A		
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A		
Surveyor Notes:		N/A			N/A			N/A			N/A		
PROW/ADA:		Not Found, R304.5.1, R304.2.2, R304.5.3			N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A			N/A		
					N/A			N/A					

