cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



	Main Of		0	4				I	014/
Intersection ID: 20407	Main Str	Main Street: CAMERON_VALLEY_PY 0			COLTSGATE_RD	Location:	SW		
ADA ID: 1EB579ED01FE	Ramp Ty	Ramp Type: PerpDiag In			ail: Fail Overall (o Severity Score:	37.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	/ith	N/A	Ramp Length (in)	82.5	No	Ramp Slope (%)	16.2
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.5
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
COLISCO	CALL AL			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
RD 6.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A CONTRACTOR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second s		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CONTRACTOR AND A				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	5			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	11 Marto	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name CA	AMERON VALLEY PY				X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	0.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	4.4
Street 2 Name	COLTSGATE RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	5.8	N/A	Clear Space?	N/A
	-				Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P) Good

