cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23067	Main Stre	et: JOHN_PRICE_RD	Cross	Cross Street: POINT_SOUTH_DR				Location: NE	
ADA ID: 1EC7E2F0E1A7	Ramp Ty	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			o Severity Score:	0
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
	A STAN	Remove & Replace Cu	rb Ramp With	N/A	Ramp Length LT (in)	55.0	N/A	Ramp Length RT (in)	51.0
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width LT (in)	58.0	Yes	Ramp Width RT (in)	58.0
				Yes	Ramp Slope LT (%)	6.2	No	Ramp Slope RT (%)	9.1
				Yes	Ramp XSlope LT (%)	1.5	No	Ramp XSlope RT (%)	7.7
				N/A	Ramp Length (in)	39.0	No	Ramp Slope (%)	9.1
				Yes	Ramp Width (in)	52.0	No	Ramp XSlope (%)	8.4
		Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	- A			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E CITER DR B				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
BOINT SOOME				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
The second secon		PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	1 1 A	Not Found, R304.2.2, R304.5.3,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 1 1	R304.3.2		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
1 543				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	JOHN PRICE RD			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign				X Walk 1 Direction	To W		X Walk 2 Direction	To S
Stop Condition-Street 2	POINT SOUTH DR				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	0.5
					X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	4.5
		Total Cost:	\$ 3200.00	N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
			• • • • • • •		Road Slope (%)	4.8		Clear Space?	N/A
					Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A
				direct services de la			N/A	Any Obstruction?	N/A
		La						Obstruction Type	
								76-	N/A
							N/A	Storm Grate/Utility Hazard?	
					a materia			Storm Grate/Utility Type	N/A
					Marrie .				N1/A

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 14.0





