

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54415	Main Sti	Cross Street: ARDREY_KELL_RD					Location:	NW	
ADA ID: 1EF8BE7EDA7D	A7D Ramp Type: Perp			/Fail: Fa	ail Overall C	o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description				Data Compliance Description		
		Remove & Replace Entire Ramp.	N/A	Ram	p Length (in)	95.0	No	Ramp Slope (%)	8.6
The Carlot And	1		Yes	Ram	p Width (in)	70.0	No	Ramp XSlope (%)	4.4
		1	N/A	Flare	e Type LT	N/A	N/A	Flare Type RT	N/A
and the second sec			N/A	Flare	e Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
The second second			N/A	Flare	e Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Land	ing Length (in)	N/A	N/A	DWS Provided?	N/A
	& BR	Surveyor Notes:	N/A	Land	ing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	A State	N/A	N/A	Land	ing Slope (%)	N/A	N/A	DWS Length (in)	N/A
NO NO	BEN &		N/A	Land	ing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second se	A State		N/A	Land	ing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
di anti anti anti anti anti anti anti ant	0		N/A	Shar	ed Landing?	N/A			
- <u>6</u> .		PROW/ADA:	N/A	Gutte	er Ponding?	N/A	N/A	Gutter Slope (%)	N/A
a longer and a set		R304.2.2, R304.5.3	N/A	Gutte	er Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	ANT RES.	,	N/A	Paint	ted X Walk1?	No	N/A	Painted X Walk2?	N/A
and the search of the	·	4		X Wa	alk 1 Direction	To S		X Walk 2 Direction	N/A
			N/A	X Wa	alk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ARDREY KELL RD	-		X Wa	alk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				alk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ram	p inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road	l Slope (%)	N/A	N/A	Clear Space?	N/A
				Road	X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A		Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	•	ruction Type			Storm Grate/Utility Type	
						N/A			N/A



Yes

Surface Condition? (G/P)

Good