


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 8183	Main Street: DR_WEBBER_AV	Cross Street: IRMA_ST	Location: SW
ADA ID: 1F63330FAAD6	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 46.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance		Description		Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	9.8				
			No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	8.9				
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
		N/A	Shared Landing?	N/A								
PROW/ADA:		N/A	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
		Not Found, R304.5.1, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A				
				X Walk 1 Direction	To N		X Walk 2 Direction	N/A				
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A				
				X Walk 1 Slope (%)	7.5		X Walk 2 Slope (%)	N/A				
				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A				
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A				
				Road Slope (%)	N/A	N/A	Clear Space?	N/A				
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
				Obstruction Type			Storm Grate/Utility Type					
					N/A			N/A				
						Yes	Surface Condition? (G/P)	Good				
Street 1 Name		DR WEBBER AV										
Stop Condition-Street 2		StopSign										
Street 2 Name		N/A										
Stop Condition-Street 1		N/A										
Total Cost:		\$	1850.00									

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	9.8
No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	8.9
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	7.5		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good

